



© 2006 Mazda Motor of America, Inc.

Subject: SPARK PLUG INSTALLATION / REMOVAL CAUTION	Bulletin No: 01-036/06
	Last Issued: 09/01/2006

APPLICABLE MODEL(S)/VINS

- 1997-2007 B-Series
- 1997-2003 Protege
- 1997-2005 Miata
- 1997-2002 626
- 1997-2002 Millenia
- 1997-2006 MPV
- 2001-2006 Tribute
- 2003-2007 Mazda6
- 2004-2007 Mazda3
- 2004-2007 RX-8
- 2006-2007 Mazda5
- 2006-2007 MX-5
- 2007 CX-7

DESCRIPTION

The use of power tools to remove or install spark plugs may cause damage to the threads in the cylinder head and/or the spark plug ceramic tip may chip off and fall into the cylinder.

Mazda does not recommend using power tools for removal or installation of spark plugs. Only use hand tools when removing or installing spark plugs.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.